



HOT WORK

PERMITS

Hot Work includes any operation producing flame, sparks, or heat. Examples of hot work include torch cutting, welding, brazing, grinding, sawing, and soldering.

A Hot Work permit is required for any hot work activity conducted outside of an area designated for hot work.

- ✓ The permit acts as a checklist to ensure precautions are taken to prevent the ignition of flammable or combustible materials in a 35-foot area surrounding the work.
- ✓ Hot Work permits must be posted in a visible location at the worksite.
- ✓ All Hot Work permits and notifications must be submitted 24 hours before the start of activities.
- ✓ Hot Work permits can be located [online](#).

